

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
15-CHETO.V,
2-

Godlington Manor, Main House
Chestertown Vicinity
Kent County
Maryland

HABS No. MD-868

Douglas Barber, Photographer 1972

Main House

- MD-868-1 GENERAL VIEW OF HOUSE AND OUTBUILDINGS, TAKEN FROM THE SOUTHWEST, WITH MILKHOUSE IN FOREGROUND
- MD-868-2 SOUTH ELEVATION, SHOWING GAMBREL ROOF WITH SHINGLES AND PENT ROOF OVER PORCH
- MD-868-3 SOUTH ELEVATION, DETAIL OF SOUTHEAST CORNER, SHOWING FLUSH SIDING (NOTE MARK OF FORMER HANDRAIL)
- MD-868-4 NORTH ELEVATION
- MD-868-5 GROUND FLOOR, EAST ROOM, EAST WALL, SHOWING BUILT IN CUPBOARD, PANELING AND FIREPLACE AND OVERMANTEL
- MD-868-6 GROUND FLOOR, EAST ROOM, EAST WALL, DETAIL OF BUILT IN CUPBOARD
- MD-868-7 GROUND FLOOR, EAST ROOM, NORTHWEST CORNER, LOOKING FROM ROOM INTO HALL
- MD-868-8 GROUND FLOOR, WEST ROOM, WEST WALL, DETAIL SHOWING FIREPLACE AND PANELING
- MD-868-9 ATTIC, EAST CHAMBER, DETAIL OF STAIRWELL IN SOUTHEAST CORNER
- MD-868-10 ATTIC, MIDDLE CHAMER, NORTH WALL
- MD-868-11 ATTIC, WEST CHAMBER, WEST WALL, VIEW OF FIREPLACE
- MD-868-12 ATTIC, WEST CHAMBER, DETAIL OF STENCILING
- MD-868-13 GROUND FLOOR, KITCHEN WING, WEST ROOM, NORTHEAST CORNER
- MD-868-14 GROUND FLOOR, KITCHEN WING, WEST ROOM, DETAIL OF BUILT IN CUPBOARD
- MD-868-15 GROUND FLOOR, KITCHEN WING, WEST ROOM, WEST WALL, VIEW OF FIREPLACE
- MD-868-16 GROUND FLOOR, KITCHEN WING, WEST ROOM, STEP LADDER IN SOUTHWEST CORNER
- MD-868-17 ATTIC, KITCHEN WING, WEST CHAMBER, STAIRHEAD IN SOUTHWEST CORNER
- MD-868-18 ATTIC, KITCHEN WING, WEST CHAMBER, EAST WALL